

GG OKNOYNYX

OKKKZQZX

(A0203/24 NOTAMR A0201/24

Q)OKAC/QILXX/I/NBO/A/000/999/2914N04759E005

A)OKKK B)2405281636 C)2406261200

E)DUE TO WIP IN NEW TERMINAL T2 LOCALIZER SIGNAL RWY 15L MIGHT
EXPEREINCE SIGNAL FLUCTUATION PILOT SHALL TAKE EXTRA CAUTION
AND REPORT ANY SIGNAL FLUCTUATIONS TO A.T.C)

يوسف التميمي
رئيس شعبة النوتام

٢٠٢٤ / ٥ / ٢٨