

(A0402/25 NOTAMN

Q)OKAC/QICXX/I/NB0/A/000/999/2914N04759E005

A)OKKK B)2508311200 C)2511301200

E)DUE TO WIP FROM CONSTRUCTION WORKS IN EAST RWY (33R/15L)

LOCALIZER SIGNAL RWY 33R MIGHT EXPERIENCE SIGNAL FLUCTUATION

PILOT SHALL TAKE EXTRA CAUTION AND REPORT ANY SIGNAL

FLUCTUATION TO A.T.C .)

31-8-2025

أحمد العبد

